

875—90.7 (89) Fees.

90.7(1) *Special inspector commission fee.* A \$55 fee shall be paid annually to the commissioner to obtain a special inspector commission pursuant to Iowa Code section 89.7.

90.7(2) *Certificate fee.* A \$40 fee shall be paid for each one-year certificate, an \$80 fee shall be paid for each two-year certificate, and a \$160 fee shall be paid for each four-year certificate.

90.7(3) *Fees for inspection.* An inspection fee for each object inspected by a division inspector shall be paid by the appropriate party as follows:

- a.* A \$55 fee for each water heater supply boiler.
- b.* A \$95 fee for each boiler, other than a water heater supply boiler, having a working pressure up to and including 450 pounds per square inch or generating between 20,000 and 100,000 pounds of steam per hour.
- c.* A \$215 fee for each boiler, other than a water heater supply boiler, having a working pressure in excess of 450 pounds per square inch and generating in excess of 100,000 pounds of steam per hour.
- d.* A \$55 fee for each pressure vessel, such as steam stills, tanks, jacket kettles, sterilizers and all other reservoirs having a working pressure of 15 pounds or more per square inch.
- e.* In addition to the applicable object's inspection fee, if the division cannot follow normal practice of scheduling inspections in a cost-effective manner due to a request by an owner or user for a customized schedule, travel expenses may be charged at the discretion of the division.
- f.* Upon receipt of a request for a state inspector to visit or inspect for a reason not required by Iowa Code chapter 89, the labor commissioner may negotiate an appropriate fee.
- g.* If a boiler or pressure vessel has to be reinspected, there shall be another inspection fee as specified above.

90.7(4) *Fees for attempted inspections.* A \$35 fee shall be charged for each attempt by a division inspector to conduct an inspection which is not completed through no fault of the division.

[**ARC 7863B**, IAB 6/17/09, effective 7/1/09; **ARC 8081B**, IAB 8/26/09, effective 9/30/09; **ARC 0319C**, IAB 9/5/12, effective 10/10/12; **ARC 1422C**, IAB 4/16/14, effective 5/21/14]